

ISO 1502:1996-02 (E)

ISO_general-purpose metric screw threads_- Gauges and gauging

Contents

	Page
1 Scope	1
2 Normative references	1
3 Symbols and abbreviations	1
4 Types of gauges	3
4.1 Gauges for external threads of workpieces and their check plugs and setting plugs	3
4.2 Gauges for internal threads of workpieces	3
5 Gauging of workpieces	3
5.1 Gauging of external threads	3
5.2 Gauging of internal threads	4
5.3 Inspection gauging	4
6 Reference temperature	4
7 Function, checking and use of gauges	4
7.1 Gauges for external threads of workpieces and their check plugs and setting plugs	5
7.2 Gauges for internal threads of workpieces	8
8 Tolerance zones for the diameters of gauges (see figures 1 and 2)	8
9 Tolerance zones for plain gauges (see figures 3 and 4)	11
10 Thread profiles for gauges	13
10.1 Profiles with complete flanks (see figures 5 and 6)	13
10.2 Profiles with truncated flanks (see figures 7 and 8)	16
10.3 Displacement of the clearance groove for a profile with truncated flanks	18
11 General features of screw gauges	19
11.1 Gauges for external threads of workpieces	19
11.2 Gauges for internal threads of workpieces	19

11.3	Blunt start of thread	19
12	Tolerances and permissible wear for pitch diameters of gauges (see tables 4 to 9)	21
13	Formulae for calculation of gauge limits	23
13.1	Screw gauges for external threads of workpieces	23
13.2	Plain gauges for the major diameters of external threads of workpieces	23
13.3	Screw gauges for internal threads of workpieces	23
13.4	Plain gauges for the minor diameters of internal threads of workpieces	23
 Annex		
A	Bibliography	27