

# DIN 32937:2006-07 (E)

## Surveillance of measuring, testing and inspection equipment - Planning, management and use of measuring, testing and inspection equipment

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
<b>1</b>	<b>Scope .....</b>	<b>3</b>
<b>2</b>	<b>Normative references .....</b>	<b>3</b>
<b>3</b>	<b>Concepts .....</b>	<b>4</b>
<b>4</b>	<b>General .....</b>	<b>4</b>
<b>5</b>	<b>Objective .....</b>	<b>5</b>
<b>6</b>	<b>Requirements .....</b>	<b>5</b>
<b>7</b>	<b>Implementation .....</b>	<b>6</b>
7.1	Planning the inspection process for verification of product conformity .....	6
7.1.1	General .....	6
7.1.2	Inspection task .....	6
7.1.3	Operating conditions .....	6
7.1.4	Specifications .....	7
7.1.5	Planning the inspection process .....	7
7.1.6	Metrological requirements .....	8
7.1.7	Selection of inspection equipment .....	8
7.1.8	Usability of inspection equipment .....	9
7.1.9	Suitability of the inspection process .....	9
7.1.10	Allocation of inspection equipment .....	9
7.2	Management and documentation .....	10
7.2.1	General .....	10
7.2.2	Procedures for setting up an inspection equipment management system .....	10
7.2.3	Identification of inspection equipment .....	11
7.2.4	Equipment data .....	11
7.2.5	Inspection equipment management system .....	13
7.3	Surveillance .....	15
7.3.1	General .....	15
7.3.2	Type of surveillance (internal/external) .....	15
7.3.3	Verification of inspection equipment .....	16
7.3.4	Verification and calibration times and intervals .....	18
7.3.5	Marking .....	19
7.3.6	Maintenance and storage of inspection equipment .....	19
7.4	Dealing with non-conformities .....	19
7.5	Changing the status or scrapping of equipment .....	20
Annex A (informative) Criteria for evaluating testing or calibration laboratories .....		21
Bibliography .....		24