

ISO 29862:2007-12 (E)

Self adhesive tapes — Determination of peel adhesion properties

Contents

	Page
Foreword.....	3
1 Scope	4
2 Normative references	5
3 Terms and definitions.....	5
4 Significance and use	5
5 Method 1 – Self adhesive tapes – Measurement of peel adhesion from stainless steel at an angle of 180°	6
6 Method 2 – Self adhesive tapes - Measurement of peel adhesion from its own backing at an angle of 180°	8
7 Method 3 – Self adhesive tapes - Measurement of peel adhesion of double sided and transfer tapes at an angle of 180°	10
8 Method 4 – Self adhesive tapes - Measurement of adhesion of the liner to an adhesive tape at an angle of 180°	11
Annex A (normative) Self adhesive tapes – Measurement of peel adhesion from a surface at low temperature	13
Annex B (normative) Self adhesive tapes – Measurement of peel adhesion from a surface at an angle of 90°	14