

ISO 29864:2007-12 (E)

Self adhesive tapes — Measurement of breaking strength and elongation at break

Contents

	page
Foreword.....	3
Introduction	4
1 Scope	5
2 Terms and definitions.....	5
3 Significance and use	5
4 Principle	5
5 Apparatus	6
6 Test sample and test pieces	7
7 Procedure	7
8 Expression of results	8
9 Test report	8