

ISO 13165-3:2016-03 (E)

Water quality - Radium-226 - Part 3: Test method using coprecipitation and gamma-spectrometry

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Symbols	2
5 Principle of the measurement	3
6 Reagents and equipment	3
6.1 Reagents	3
6.2 Equipment	4
7 Sampling	4
7.1 Sample collection	4
7.2 Sample transport and storage	4
8 Procedures	4
8.1 Blank sample preparation	4
8.2 Sample preparation	5
8.3 Counting procedure	5
9 Quality assurance and quality control programme	5
9.1 General	5
9.2 Influence quantities	6
9.3 Instrument verification	6
9.4 Method verification	6
9.5 Demonstration of analyst capability	6
10 Expression of results	6
10.1 General	6
10.2 Water-soluble ^{226}Ra activity concentration	7
10.3 Standard uncertainty of activity concentration	7
10.4 Decision threshold	7
10.5 Detection limit	7
10.6 Limits of the confidence interval	8
10.7 Corrections for contributions from other radionuclides and background	8
10.7.1 General	8
10.7.2 Contribution from other radionuclides	9
10.7.3 Contribution from background	10
11 Expression of results	10
Annex A (informative) Uranium and its decay chain	12
Bibliography	14