

# ISO 13165-3:2024-12 (E)

## Water quality - Radium-226 - Part 3: Test method using coprecipitation and gamma-ray spectrometry

---

<b>Contents</b>		<b>Page</b>
Foreword.....		iv
Introduction.....		v
<b>1</b> <b>Scope</b> .....		<b>1</b>
<b>2</b> <b>Normative references</b> .....		<b>1</b>
<b>3</b> <b>Terms and definitions</b> .....		<b>2</b>
<b>4</b> <b>Symbols</b> .....		<b>2</b>
<b>5</b> <b>Principle</b> .....		<b>3</b>
<b>6</b> <b>Reagents and equipment</b> .....		<b>4</b>
6.1    Reagents.....		4
6.2    Equipment.....		4
<b>7</b> <b>Sampling</b> .....		<b>5</b>
7.1    General.....		5
7.2    Sample collection.....		5
7.3    Sample transportation and storage.....		5
<b>8</b> <b>Procedure</b> .....		<b>5</b>
8.1    Blank sample preparation.....		5
8.2    Sample preparation.....		5
8.3    Counting procedure.....		6
<b>9</b> <b>Quality assurance and quality control programme</b> .....		<b>6</b>
9.1    General.....		6
9.2    Interferences.....		6
9.3    Method verification.....		7
9.4    Demonstration of analyst capability.....		7
<b>10</b> <b>Expression of results</b> .....		<b>7</b>
10.1    General.....		7
10.2    Water-soluble <sup>226</sup> Ra activity concentration.....		7
10.3    Standard uncertainty of activity concentration.....		8
10.4    Decision threshold.....		8
10.5    Detection limit.....		9
10.6    Limits of the coverage intervals.....		9
10.6.1    Limits of the probabilistically symmetric coverage interval.....		9
10.6.2    Shortest coverage interval.....		10
10.7    Corrections for contributions from other radionuclides and background.....		10
10.7.1    General.....		10
10.7.2    Contribution from other radionuclides.....		10
10.7.3    Contribution from background.....		11
<b>11</b> <b>Test report</b> .....		<b>12</b>
<b>Annex A</b> (informative) <b>Uranium-238 decay chain</b> .....		<b>14</b>
<b>Bibliography</b> .....		<b>15</b>