

# ISO 3547-5:2007-10 (E)

## Plain bearings - Wrapped bushes - Part 5: Checking the outside diameter

---

<b>Contents</b>		<b>Page</b>
	<b>Foreword</b> .....	<b>iv</b>
<b>1</b>	<b>Scope</b> .....	<b>1</b>
<b>2</b>	<b>Normative references</b> .....	<b>1</b>
<b>3</b>	<b>Symbols and units</b> .....	<b>2</b>
<b>4</b>	<b>Outside diameter, Do</b> .....	<b>2</b>
<b>5</b>	<b>Purpose of checking</b> .....	<b>3</b>
<b>6</b>	<b>Methods of checking</b> .....	<b>3</b>
<b>7</b>	<b>Selection of checking method for outside diameter</b> .....	<b>3</b>
<b>11</b>	<b>Specifications on drawings of bushes</b> .....	<b>14</b>
<b>12</b>	<b>Specifications for control of the checking equipment</b> .....	<b>14</b>
	<b>Bibliography</b> .....	<b>15</b>