

ISO 3548-2:2020 (E)

Plain bearings — Thin-walled half bearings with or without flange — Part 2: Measurement of wall thickness and flange thickness

Contents

	Foreword
1	Scope
2	Normative references
3	Terms and definition
4	Symbols and units
5	Purpose of checking
6	Checking methods
6.1	Measuring principle of wall thickness
6.2	Line measurement around the circumference
6.3	Line measurement in axial direction
6.4	Point measurement
6.5	Grading of bearings
6.6	Eccentric bore
6.7	Measuring principle for flange thickness
6.8	Measuring point for flange thickness
7	Requirements for measuring equipment and specimen for the contact method
7.1	Tip-radius for measuring pin on the outside surface
7.2	Tip-radius for measuring pin on the inside surface
7.3	Measuring pin load
7.4	Set-up
7.5	Periodical control
7.6	Measurement failures on the inside and/or outside surface
8	Checking of measuring equipment

Page count: 10