

# DIN EN 326-2:2010-12 (E)

## Wood-based panels - Sampling, cutting and inspection - Part 2: Initial type testing and factory production control

---

<b>Contents</b>		<b>Page</b>
Foreword .....		4
1	Scope .....	5
2	Normative references .....	5
3	Terms and definitions .....	5
4	Symbols and indices .....	7
4.1	Letter symbols (see also EN 326-1:1994) .....	7
4.2	Indices (see also EN 326-1:1994) .....	9
5	Initial type testing (ITT) .....	9
5.1	General .....	9
5.2	Initial type testing by variables .....	9
5.2.1	General .....	9
5.2.2	Sampling of panels .....	10
5.2.3	Evaluation .....	10
5.3	Initial type testing by attributes .....	12
5.3.1	Sampling .....	12
5.3.2	Evaluation .....	12
6	Factory production control .....	13
6.1	General .....	13
6.2	Sampling .....	13
6.2.1	General .....	13
6.2.2	Dimensional tolerances, squareness and edge straightness .....	13
6.2.3	Other properties assessed as attributes and not included in 6.2.1 or 6.2.2 .....	13
6.2.4	Sampling and cutting of test pieces .....	14
6.3	Factory production control by variables .....	14
6.3.1	Characteristics .....	14
6.3.2	Product types .....	14
6.4	Control of production .....	15
6.4.1	General .....	15
6.4.2	Factory production control by variables for batch production .....	15
6.4.3	Factory production control by attributes for batch production .....	17
6.4.4	Internal records of an established product .....	19
6.5	Initial inspection of factory and factory production control (FPC) .....	19
6.6	Continuous surveillance, assessment and approval of the factory production control .....	20
Annex A (informative)	Example of initial type testing by variables - Evaluation of bending strength of particleboards (see 5.2) .....	21
A.1	Example .....	21
A.2	Sampling (see 5.1.2) .....	21
A.3	Test results, records and evaluation (see 5.2.3 and EN 326-1:1994, Clause 7) .....	21
Annex B (informative)	Factory production control by variables - Example: Batch production (see 6.4.2) .....	23
B.1	General .....	23

B.2	Sampling .....	23
B.3	Testing .....	23
B.4	Calculation and recording of test results of the first sample .....	23
B.4.1	Example for the case that the first sample of one panel fulfils the panel characteristic requirement .....	23
B.4.2	Example for the case that the first sample of one panel does not fulfil the panel characteristic requirement .....	24
<b>Annex C (informative) Example of initial type testing attributes - Evaluation of bonding quality of plywood (see 6.4.3.1) .....</b>		<b>27</b>
C.1	Example .....	27
C.2	Sampling plan .....	27
C.3	Sampling (see 5.3.1) .....	27
C.4	Test data and evaluation of bond shear strength and apparent cohesive wood fibre failure percentage .....	27
C.4.1	General .....	27
C.4.2	First sample .....	28
C.4.3	Second sample .....	29
C.5	Single sampling plan .....	30
<b>Annex D (informative) Control of factory production control records - Examples of the determination of differences between factory testing and external testing (see 6.6) .....</b>		<b>31</b>
D.1	General .....	31
D.1.1	Use of unconditioned test pieces .....	31
D.1.2	Paired testing .....	31
D.2	Example (1): Swelling in thickness tested according to EN 317 .....	32
D.2.1	Sample of example (1) .....	32
D.2.2	Control of variability .....	32
D.3	Example (2): Internal bond tested according to EN 319 .....	34
D.3.1	General .....	34
D.3.2	Sample of example (2) .....	34
D.3.3	Control of variability .....	34
D.4	Determination of a significant difference between the results from the alternative test procedure and from the standard reference test method .....	35
<b>Annex E (informative) Example of the calculation of a linear correlation (see 7.2) .....</b>		<b>37</b>
<b>Annex F (informative) Example of the determination of a significant difference between the results from the alternative test procedure and from the standard reference test method (see 6.4.5) in accordance with EN 13986 .....</b>		<b>40</b>
F.1	General .....	40
F.2	Control of variability (see Annex D) .....	41
F.3	Determination of a significant difference (see Annex D) .....	41
<b>Bibliography .....</b>		<b>42</b>