

DIN EN 16211:2015-09 (E)

Ventilation for buildings - Measurement of air flows on site - Methods

Contents		Page
Foreword		4
1	Scope	5
2	Normative references	5
3	Terms, definitions and symbols	5
3.1	Terms and definitions	5
3.2	Symbols	5
4	Principles and parameters of influence	7
4.1	Hydraulic diameter	7
4.2	Flow disturbances	7
4.3	Air density,	7
4.4	Dynamic pressure, p_d	7
4.5	Corrections for air density,	8
5	Sources of errors	8
5.1	General	8
5.2	Systematic errors	9
5.3	Random errors	10
6	Measurement uncertainty	10
6.1	Overall measurement uncertainty	10
6.2	Standard instrument uncertainty, u_1	11
6.3	Standard method uncertainty, u_2	11
6.4	Standard reading uncertainty, u_3	11
6.5	Expanded measurement uncertainty, U_m	11
7	Measurement requirements	12
7.1	Method requirements and corrections	12
7.2	Measurements using a manometer	12
7.3	Measurements using an anemometer	13
7.4	Measurements using Pitot static tube	13
7.5	Measuring temperature and barometric pressure	13
7.6	Mean value calculation of measurement signal	13
8	Methods for measurement of air flows in ducts - ID (In Duct) methods	13
8.1	Overview of recommended methods	13
8.2	Point velocity measurements using a Pitot static tube (method ID 1) or an anemometer (method ID 2)	14
8.2.1	Method description	14
8.2.2	Preparations to be made at the site of measurement	15
8.2.3	Measurement procedure	18
8.2.4	Corrections of measured values and calculation of air flow	19
8.2.5	Standard method uncertainty	20
8.3	Fixed devices for flow measurement - Method ID 3	20
8.3.1	Method description	20
8.3.2	Preparations of measurements -- Equipment	20
8.3.3	Measurement procedure	21
8.3.4	Correction of measured values	21
8.3.5	Standard method uncertainty	21

8.4	Tracer gas measurement - Method ID 4	21
8.4.1	Method description	21
8.4.2	Equipment	22
8.4.3	Calculation of air flow	23
8.4.4	Standard measurement uncertainty	23
8.4.5	Conditions for homogeneous mixing of tracer gas	24
9	Methods for measurement of air flows in Supply ATDs (air terminal devices) - ST (Supply (Air) Terminal (Devices)) methods	25
9.1	Overview of recommended methods	25
9.2	Measurement of reference pressure - Method ST 1	25
9.2.1	Introduction	25
9.2.2	Equipment	26
9.2.3	Correction of measured values	26
9.2.4	Standard method uncertainty	27
9.3	Measurement with tight bag - Method ST 2	27
9.3.1	Method description	27
9.3.2	Limitations	27
9.3.3	Equipment	27
9.3.4	Preparation	28
9.3.5	Measurement	28
9.3.6	Correction of measured values	28
9.3.7	Standard method uncertainty	28
9.4	Measurements with flow hood - Method ST 3	28
9.4.1	Introduction	28
9.4.2	Equipment	29
9.4.3	Measurement	30
9.4.4	Correction of measured values	31
9.4.5	Standard method uncertainty	31
10	Methods for Exhaust ATDs (air terminal devices) - ET (Exhaust (Air) Terminal (Devices)) methods	32
10.1	Overview of recommended methods	32
10.2	Measurement of reference pressure at exhaust ATD - Method ET 1	32
10.2.1	Method description	32
10.2.2	Limitations	33
10.2.3	Equipment	33
10.2.4	Correction of measured values	33
10.2.5	Standard method uncertainty	34
10.3	Measurement using a flow hood - Method ET 2	34
10.3.1	Introduction	34
10.3.2	Equipment	34
10.3.3	Measurement	35
10.3.4	Correction of measured values	36
10.3.5	Standard method uncertainty	36
	Annex A (informative) Uncertainties	37
A.1	Examples of calculations	37
A.2	Compound uncertainties	38
A.3	Example of applications	38
	Bibliography	39