

# ISO/IEC TR 24720:2008-06 (E)

## Information technology - Automatic identification and data capture techniques - Guidelines for direct part marking (DPM)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Abbreviated terms .....	2
5	Overview of DPM .....	2
5.1	DPM methods .....	2
5.2	Reasons for utilizing DPM .....	3
6	Marking method selection .....	3
7	Marking methods .....	6
8	Cleaning .....	6
9	Marking surface preparation .....	6
9.1	Assessment .....	6
9.2	Protective coatings .....	7
10	Human readable marking .....	8
11	Symbol quality .....	8
12	Reading and grading DPM symbols .....	9
13	Verification .....	9
13.1	General .....	9
13.2	Configuration .....	9
13.3	Possible equipment setup .....	10
14	Imagers for direct part marking applications .....	11
14.1	General description .....	11
14.2	Fixed-mount imagers .....	11
14.3	Presentation imager .....	12
14.4	Hand-held imager .....	12
Annex A (informative) Intrusive marking methods .....		14
A.1	Intrusive marking .....	14
A.2	Re-marking requirements using intrusive marking methods .....	15
A.3	Laser marking .....	15
A.4	Dot peen marking .....	18
A.5	Other Intrusive marking methods .....	20
Annex B (informative) Non-intrusive marking methods .....		22
B.1	Non-intrusive marking methods .....	22
B.2	Ink jet marking .....	22

<b>B.3</b>	<b>Fabric embroidery/weaving .....</b>	<b>25</b>
<b>B.4</b>	<b>Forge, cast .....</b>	<b>26</b>
<b>B.5</b>	<b>Laser bonding .....</b>	<b>27</b>
<b>B.6</b>	<b>Laser engineered net shaping (LENS) .....</b>	<b>27</b>
<b>B.7</b>	<b>Screen printing .....</b>	<b>28</b>
<b>B.8</b>	<b>Stencil .....</b>	<b>29</b>
<b>Annex C (informative) Rockwell Hardness .....</b>		<b>30</b>
<b>Bibliography .....</b>		<b>32</b>