

ISO/IEC TR 24720:2008-06 (E)

Information technology - Automatic identification and data capture techniques - Guidelines for direct part marking (DPM)

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Abbreviated terms	2
5	Overview of DPM	2
5.1	DPM methods	2
5.2	Reasons for utilizing DPM	3
6	Marking method selection	3
7	Marking methods	6
8	Cleaning	6
9	Marking surface preparation	6
9.1	Assessment	6
9.2	Protective coatings	7
10	Human readable marking	8
11	Symbol quality	8
12	Reading and grading DPM symbols	9
13	Verification	9
13.1	General	9
13.2	Configuration	9
13.3	Possible equipment setup	10
14	Imagers for direct part marking applications	11
14.1	General description	11
14.2	Fixed-mount imagers	11
14.3	Presentation imager	12
14.4	Hand-held imager	12
Annex A (informative) Intrusive marking methods		14
A.1	Intrusive marking	14
A.2	Re-marking requirements using intrusive marking methods	15
A.3	Laser marking	15
A.4	Dot peen marking	18
A.5	Other Intrusive marking methods	20
Annex B (informative) Non-intrusive marking methods		22
B.1	Non-intrusive marking methods	22
B.2	Ink jet marking	22

B.3	Fabric embroidery/weaving	25
B.4	Forge, cast	26
B.5	Laser bonding	27
B.6	Laser engineered net shaping (LENS)	27
B.7	Screen printing	28
B.8	Stencil	29
Annex C (informative) Rockwell Hardness		30
Bibliography		32