

# E DIN EN 4533-001:2024-06 (E)

Erscheinungsdatum: 2024-04-26

Aerospace series - Fibre optic systems - Handbook - Part 001: Termination methods and tools; English version prEN 4533-001:2024

---

## Contents

Page

European foreword .....	4
Introduction.....	5
1 Scope.....	6
1.1 General.....	6
1.2 Need for high-integrity terminations .....	6
2 Normative references.....	7
3 Terms and definitions.....	7
4 Component selection .....	7
4.1 Elements.....	7
4.2 Fibre optic cables .....	7
4.2.1 General.....	7
4.2.2 Cable construction.....	8
4.2.3 Fibre choice.....	9
4.2.4 Cladding materials .....	11
4.3 Primary buffer materials .....	11
4.3.1 Function.....	11
4.3.2 Acrylate.....	12
4.3.3 Polyimide.....	12
4.3.4 Silicone.....	12
4.3.5 Strength members .....	12
4.4 Outer jacket.....	13
4.5 Fibre optic interconnects (connectors).....	13
4.5.1 Introduction.....	13
4.5.2 The optical interface.....	14
4.5.3 Single-way interconnects/connectors .....	20
4.5.4 Multi-way interconnects/connectors .....	20
4.5.5 Choice of tooling.....	21
5 Health and safety aspects.....	22
5.1 General.....	22
5.2 Chemicals.....	22
5.3 Sharps.....	23
6 Termination process .....	23
6.1 Objective .....	23
6.2 Cable preparation .....	24
6.2.1 General.....	24
6.2.2 Cutting to length.....	24
6.2.3 Removal of outer jacket.....	25
6.2.4 Cable handling tools (gripping the cable).....	30
6.2.5 Strength member trimming/removal .....	31
6.3 Removal of secondary coating(s).....	32
6.4 Removal of primary coatings.....	32
6.4.1 General.....	32
6.4.2 Mechanical techniques for primary coating removal.....	33

6.4.3	Alternative techniques.....	39
6.4.4	Troublesome coatings — Polyimide and Silicone.....	40
6.4.5	Evidence of strength reduction when stripping primary buffer coatings.....	42
6.4.6	To clean or not to clean .....	43
6.5	Adhesives.....	44
6.5.1	General .....	44
6.5.2	Adhesive types.....	44
6.5.3	The importance of glass transition temperature ( $T_g$ ) .....	46
6.5.4	Epoxy cure schedule .....	48
6.5.5	Usability .....	50
6.5.6	Qualification .....	54
6.6	Connector preparation .....	54
6.6.1	Dry fitting .....	54
6.7	Attachment of fibre to the terminus .....	56
6.7.1	Application of adhesive .....	56
6.7.2	Inserting fibre 'best-practice'.....	59
6.8	Adhesive cure.....	63
6.8.1	General .....	63
6.8.2	Orientation.....	63
6.8.3	Curing equipment.....	63
6.9	Excess fibre removal.....	67
6.9.1	General .....	67
6.9.2	Post-cure rough cleaving .....	67
6.9.3	Pre-cleave.....	69
6.9.4	Safety.....	69
6.9.5	Cleaving tools .....	69
6.9.6	Sprung blade hand tools.....	70
6.9.7	Cleaving fibres in multi-fibre ferrules .....	71
6.10	Polishing .....	71
6.10.1	Rationale.....	71
6.10.2	Performance metrics.....	71
6.10.3	End-face geometries .....	71
6.10.4	End-face geometry parameters .....	72
6.10.5	Polishing stages.....	81
6.10.6	Methods for controlling end-face geometry .....	95
7	Beginning of life inspection .....	101
7.1	General .....	101
7.2	Optical or visual inspection .....	101
7.3	Interferometric inspection .....	103
7.3.1	General .....	103
7.3.2	Inspection and pass/fail criteria.....	105
	Bibliography .....	108