

# ISO 8642:2008-09 (E)

## Aerospace - Self-locking nuts with maximum operating temperature greater than 425 °C - Test methods

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b> .....		<b>iv</b>
<b>1</b>	<b>Scope</b> .....	<b>1</b>
<b>2</b>	<b>Normative references</b> .....	<b>1</b>
<b>3</b>	<b>Inspections and tests</b> .....	<b>1</b>
<b>3.1</b>	<b>Hardness test</b> .....	<b>1</b>
<b>3.2</b>	<b>Bearing surface squareness test</b> .....	<b>2</b>
<b>3.3</b>	<b>Axial load test</b> .....	<b>4</b>
<b>3.4</b>	<b>Wrenching feature test</b> .....	<b>5</b>
<b>3.5</b>	<b>Torque-out test</b> .....	<b>7</b>
<b>3.6</b>	<b>Test of no rotation of the captive washer</b> .....	<b>8</b>
<b>3.7</b>	<b>Push-out test</b> .....	<b>9</b>
<b>3.8</b>	<b>Self-locking torque at ambient temperature</b> .....	<b>10</b>
<b>3.9</b>	<b>Self-locking torque at ambient temperature after heat soak at maximum operating temperature</b> .....	<b>12</b>
<b>3.10</b>	<b>Permanent set test</b> .....	<b>15</b>
<b>3.11</b>	<b>Vibration test</b> .....	<b>17</b>
<b>3.12</b>	<b>Swaging test</b> .....	<b>20</b>