

# DIN EN 16602-70-05:2015-01 (E)

Space product assurance - Detection of organic contamination surfaces by infrared spectroscopy; English version EN 16602-70-05:2014

---

Contents	Page
<b>Foreword</b> .....	<b>5</b>
<b>1 Scope</b> .....	<b>7</b>
<b>2 Normative references</b> .....	<b>8</b>
<b>3 Terms, definitions and abbreviated terms</b> .....	<b>9</b>
3.1 Terms defined in other standards .....	9
3.2 Terms specific to the present standard .....	9
3.3 Abbreviated terms.....	11
<b>4 Principles</b> .....	<b>13</b>
<b>5 Requirements</b> .....	<b>14</b>
5.1 Preparatory activities .....	14
5.1.1 Hazard, health and safety precautions .....	14
5.1.2 Facilities .....	14
5.1.3 Materials .....	15
5.1.4 Handling.....	15
5.1.5 Equipment.....	15
5.1.6 Miscellaneous items .....	16
5.2 Procedure for sampling and analysis .....	17
5.2.1 Summary .....	17
5.2.2 Direct method.....	17
5.2.3 Indirect method .....	17
5.3 Reporting of calibration and test data.....	21
5.4 Quality assurance .....	21
5.4.1 Data .....	21
5.4.2 Nonconformance.....	21
5.4.3 Calibration.....	21
5.4.4 Traceability .....	25
5.4.5 Training.....	25
5.5 Audit of measurement equipment .....	26
5.5.1 General .....	26

5.5.2	Audit of the system (acceptance) .....	26
5.5.3	Annual regular review (maintenance) of the system .....	27
5.5.4	Special review .....	27
<b>Annex A (normative) Calibration and test results – DRD .....</b>		<b>28</b>
<b>Annex B (informative) Selection criteria for equipment and accessories for performing the infrared analysis of organic contamination .....</b>		<b>30</b>
<b>Annex C (informative) Calibration of infrared equipment .....</b>		<b>35</b>
<b>Annex D (informative) Interpretation of infrared spectra .....</b>		<b>40</b>
<b>Annex E (informative) The use of molecular witness plates for contamination control .....</b>		<b>44</b>
<b>Annex F (informative) Collecting molecular contamination from surfaces by wiping and rinsing .....</b>		<b>49</b>
<b>Annex G (informative) Contact test .....</b>		<b>54</b>
<b>Annex H (informative) Immersion test .....</b>		<b>56</b>
<b>Figures</b>		
Figure 5-1: Sampling and analysis procedure flow chart .....		20
Figure C-1 : Example for a calibration curve .....		38
Figure C-2 : Measurement of peak heights .....		39
Figure D-1 : Characteristic spectrum of bis (2-ethylhexyl) phthalate .....		41
Figure D-2 : Characteristic spectrum of a long chain aliphatic hydrocarbon .....		41
Figure D-3 : Characteristic spectrum of poly (dimethylsiloxane) .....		41
Figure D-4 : Characteristic spectrum of poly (methylphenylsiloxane) .....		41
Figure E-1 : Witness plate holder and witness plate used for organic contamination control .....		44
Figure E-2 : Example of a witness plate information sheet .....		48
Figure F-1 : Example of a sample information form .....		53
<b>Tables</b>		
Table 5-1: Standard materials used for the IR analysis .....		22
Table B-1 : Important properties of common window materials used for infrared spectroscopy .....		33
Table B-2 : Examples of compound references and suppliers .....		34
Table C-1 : Volumes to be applied from stock solutions and respective target amounts .....		38
Table C-2 : Example results of the direct calibration method .....		39
Table D-1 : Assignment of infrared absorption bands for the four main groups of contaminants .....		42