

DIN EN 16602-70-46:2015-06 (E)

Space product assurance - Requirements for manufacturing and procurement of threaded fasteners; English version EN 16602-70-46:2014

Content	page
Foreword	4
1 Scope	5
2 Normative references	6
3 Terms, definitions and abbreviated terms	8
3.1 Terms defined in other standards	8
3.2 Terms specific to the present standard	8
3.3 Abbreviated terms	9
4 Requirements	10
4.1 Fabrication	10
4.1.1 General	10
4.1.2 Raw material	10
4.1.3 Head forming	10
4.1.4 Heat treatment	11
4.1.5 Head-to-shank fillet rolling	11
4.1.6 Threads	11
4.1.7 Identification marking	12
4.1.8 Surface treatment	12
4.1.9 Workmanship, handling and packaging	12
4.2 Dimensional and metallurgical requirements	13
4.2.1 General	13
4.2.2 Nominal dimensions	13
4.2.3 Head-to-shank fillet	13
4.2.4 Non-destructive inspections	14
4.2.5 Metallurgical examination	15
4.2.6 Measurement of hydrogen content	16
4.2.7 Outgassing and offgassing	16
4.3 Mechanical testing	17

4.3.1	General	17
4.3.2	Hardness test	17
4.3.3	Tensile test	18
4.3.4	Shear test	19
4.3.5	Fatigue test	19
4.3.6	Creep test	20
4.3.7	Corrosion test	22
4.3.8	Stress-corrosion test.....	22
4.4	Quality assurance	23
4.4.1	General	23
4.4.2	Quality requirements.....	23
Annex A (normative) Customer specification document for threaded fasteners – DRD.....		26
Annex B (normative) Product conformance report (PCR) – DRD		28
Annex C (informative) Inspection levels, acceptance quality limits (AQL) and limiting quality levels (LQ) for inspection of fasteners		30
Bibliography.....		32

Figures

Figure 4-1: Tolerance of head-to-shank fillet profile	14
Figure 4-2: Location of microsections for metallurgical examination.....	15
Figure 4-3: Area delimiting interruptions in grain flow in the head-to-shank region.....	16
Figure 4-4: Example of a regular grain flow in a threaded surface.....	16
Figure 4-5: Locations for hardness testing (indicated with cross symbol)	18
Figure 4-6: Loading schematic for tensile testing of threaded fasteners	21
Figure 4-7: Schematic of an example of double-shear loading jigs.....	22

Tables

Table 4-1: Maximum allowed values of the extension C of the distorted area shown in Figure 4-1 14

Table C- 1: Inspection levels, acceptance quality limits (AQL) and limiting quality levels (LQ) for inspection of fasteners.....	30
--	----