

ISO 14952-3:2003-11 (E)

Space systems - Surface cleanliness of fluid systems - Part 3: Analytical procedures for the determination of non-volatile residues and particulate contamination

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Acceptance inspection	2
4.1	General	2
4.2	Visual inspection	2
4.3	Acidity and alkalinity test	2
4.4	Acceptance inspection of items cleaned in a controlled environment	2
4.5	Acceptance inspection of items cleaned in the field	6
4.6	Acceptance inspection of packaging materials	7
4.7	Acceptance inspection of items by functional test	9
5	Sampling and analytical practices	9
5.1	Cleanliness level test methods	9
5.2	Microscopic particle population	12
5.3	Gravimetric NVR analysis method	12
5.4	Aqueous ultrasonic sampling and total carbon (TC) NVR analysis	13
Annex A (informative) Sensitivity factor calculation		15