

# ISO 5398-3:2007-08 (E)

Leather — Chemical determination of chromic oxide content —  
Part 3: Quantification by atomic absorption spectrometry

---

<b>Contents</b>		Page
Foreword.....		iv
Introduction .....		v
1 Scope .....		1
2 Normative references .....		1
3 Terms and definitions .....		1
4 Principle.....		1
5 Sampling and sample preparation .....		2
6 Reagents .....		2
6.1 Wet oxidation method .....		2
6.2 Atomic absorption spectrometry .....		2
7 Apparatus .....		2
8 Methods .....		3
8.1 Preparation of analytical solution.....		3
8.2 Measurement of the aqueous solution.....		3
9 Calculation and expression of results.....		4
10 Test report .....		5
Annex A (informative) Determination of water and other volatile matter .....		6