

# ISO/TTA 6:2007-10 (E)

Code of practice for creep/fatigue testing of cracked components

---

<b>Contents</b>		<b>Page</b>
<b>1</b>	<b>EXECUTIVE SUMMARY .....</b>	<b>1</b>
<b>2</b>	<b>SCOPE.....</b>	<b>1</b>
<b>3</b>	<b>SPECIFIC OBJECTIVES.....</b>	<b>2</b>
<b>4</b>	<b>INTRODUCTION.....</b>	<b>2</b>
4.1	Background to VAMAS Creep Crack Growth Initiatives .....	3
4.2	Background to Industrial needs for validated Test Data .....	3
4.3	Relevance of Testing Methods to Life Assessment Codes .....	4
4.3.1	Background to Life Assessment Codes .....	4
4.3.2	Relation between laboratory tests and Component Assessment Codes .....	5
4.3.3	Factors involved in the development of assessment codes .....	5
4.4	Requirements for the VAMAS TWA 25 CoP .....	6
4.5	ISO requirements .....	6
4.5.1	ISO Technology Trend Assessment (ISO/TTA).....	7
<b>5</b>	<b>Acknowledgements .....</b>	<b>7</b>
5.1	List of participants in VAMAS TWS25.....	7
<b>6</b>	<b>NOMENCLATURE AND ABBREVIATIONS.....</b>	<b>8</b>
6.1	Nomenclatures .....	8
6.2	Listing of abbreviations.....	9
<b>7</b>	<b>DESCRIPTION OF CREEP AND FATIGUE CRACKING.....</b>	<b>10</b>
7.1	Failure due Creep Crack Growth (CCG).....	10
7.2	Creep Crack Initiation (CCI) .....	10
7.3	Transient crack growth conditions .....	10
7.4	Steady state Creep Cracking (CCG).....	10
7.5	Fatigue and Creep/Fatigue Crack Growth (FCG and CFCG) .....	11
7.5.1	Failure due to fatigue.....	11
7.5.2	Creep/Fatigue interaction.....	11
7.6	Factors affecting CCI, CCG and CFCG .....	11
7.6.1	Creep properties .....	11
7.6.2	Metallurgical effects.....	12
7.6.3	Presence of residual stress fields .....	12
7.6.4	Aggressive environments .....	12
7.6.5	Anisotropic and inhomogeneous material characteristics .....	12
<b>8</b>	<b>TEST METHODS .....</b>	<b>13</b>
8.1	Overview .....	13
8.2	Test Geometries .....	13
8.3	Experimental Test Methods .....	14
8.3.1	Material procurement.....	14
8.3.2	Specimen selection.....	14
8.3.3	Crack-plane orientation .....	14
8.3.4	Specimen machining .....	14
8.3.5	Specific size requirements.....	15
8.3.6	Specific side-grooving requirements.....	15
8.3.7	Shape of the crack front.....	15
8.3.8	Pre-cracking to introduce a sharp flat crack front .....	15
8.3.9	Pre-cracking for CCI tests .....	15
8.3.10	Crack length measurements .....	16
8.3.11	The use of Potential Drop (PD) .....	16
8.3.12	Preparing the specimens for PD leads .....	16
8.3.13	Specimen setup.....	16

8.3.14	Loading and creep displacement measurements .....	16
8.3.15	Displacement gauge .....	17
8.3.16	Heating of the specimens .....	17
8.3.17	Initial pre-load .....	17
8.3.18	Monitoring the temperature .....	17
8.3.19	Unplanned temperature excursions .....	17
8.3.20	Initial pre-load .....	18
8.3.21	Specimen loading .....	18
8.4	Data Collection .....	18
8.4.1	Detailed test and data monitoring .....	18
8.4.2	Data logging .....	18
8.4.3	Displacement measurements .....	18
8.5	Post-Test Measurements .....	19
8.5.1	Measurement of the final crack front .....	19
8.5.2	Crack tip bowing .....	19
8.5.3	Crack extension criteria .....	19
8.5.4	Crack deviation criteria .....	19
8.6	Recommended Minimum Number and Duration for Tests .....	20
8.6.1	Batch to batch variability .....	20
8.6.2	Minimum test requirements .....	20
8.6.3	Single point data per test .....	21
8.6.4	Multiple points data per test .....	21
8.6.5	Test duration requirements .....	21
8.7	Sensitivity and Accuracy Limits of the Results .....	21
8.7.1	Effects of data variability on correlation for FCG, CCG and CCI .....	21
8.8	Preparation of Test Data .....	22
8.8.1	Data collection .....	22
8.8.2	Time at which the test should be stopped .....	22
8.8.3	Smoothing the PD output data .....	22
8.8.4	Deriving the crack length from the PD output .....	22
8.8.5	Recommended number of data points .....	23
8.8.6	Calculating cracking and displacement rates .....	23
9	DATA ANALYSIS PROCEDURES .....	23
9.1	Choosing an appropriate CCI or CCG rate Correlating Parameter .....	23
9.1.1	Choice of parameter for correlating CCG .....	23
9.1.2	Choice of the $C^*$ term for CCG rate .....	23
9.1.3	Choice of parameter for CCI .....	24
9.2	Definitions for the relevant Fracture Mechanics Parameters .....	24
9.2.1	Stress intensity factor, $K$ .....	24
9.2.2	J-integral .....	24
9.2.3	The $C^*$ parameter .....	24
9.2.4	Creep zone .....	25
9.2.5	Steady state creep .....	25
9.2.6	The $C_t$ parameter .....	26
9.2.7	Small-scale creep .....	26
9.2.8	Interpretation of $C^*$ parameter .....	26
9.2.9	Time Dependant Failure Assessment Diagram (TDFAD) for CCI .....	26
9.2.10	The $Q^*$ Parameter .....	27
9.3	Criteria for Validity Checks of $C^*$ and $K$ .....	27
9.3.1	Check for validity of $C^*$ .....	27
9.3.2	Components of displacement rates .....	27
9.3.3	Validity criteria for $C^*$ for highly ductile materials .....	28
9.3.4	Validity criteria for creep brittle materials .....	29
9.3.5	Transition time criteria for $C^*$ .....	29
10	REPORTING PROCEDURES .....	30
10.1	Details of test information to be reported .....	30
10.1.1	Report of findings .....	30
10.1.2	Pedigree of the material .....	30
10.1.3	Material properties to be logged .....	30

10.1.4	Test machine description.....	30
10.1.5	Details of starter crack .....	30
10.1.6	Details for loading.....	30
10.1.7	Report of data analysis.....	30
10.1.8	Plots of data.....	31
10.1.9	Tabulation of results.....	31
10.1.10	Photographic/micrographic evidence.....	31
10.1.11	Treatment of anomalous data.....	31
11	<b>CORRELATING CRACK GROWTH USING FRACTURE MECHANICS.....</b>	<b>31</b>
11.1	CCG rate analysis .....	31
11.2	Crack Initiation (CCI) Analysis.....	32
11.3	FCG rate Analysis .....	32
11.4	Creep/fatigue crack growth rate analysis.....	33
12	<b>Methods for Calculating the C* Parameter.....</b>	<b>33</b>
12.1	Experimental Estimates of C* .....	33
12.2	Reference Stress Method of Estimating C*.....	34
13	<b>APPENDIX I.....</b>	<b>36</b>
13.1	Test Specimen Geometries.....	36
13.2	Geometry Definitions for Laboratory Specimens.....	36
14	<b>SPECIMEN FRACTURE MECHANICS PARAMETER SOLUTIONS.....</b>	<b>38</b>
14.1	Stress Intensity Factor $K$ .....	38
14.2	Solutions for the Y function.....	38
14.2.1	Y factor for C(T).....	39
14.2.2	Y factor for CS(T).....	39
14.2.3	Y factor for SEN(T).....	39
14.2.4	Y factor for SEN(B) (3 Point Bend Specimen).....	39
14.2.5	Y factor for DEN(T).....	40
14.2.6	Y factor for M(T).....	40
14.3	C* Solutions.....	40
14.4	Reference Stress ( $\sigma_{ref}$ ) Solutions.....	41
14.4.1	$\sigma_{ref}$ for C(T).....	41
14.4.2	$\sigma_{ref}$ for CS(T).....	42
14.4.3	$\sigma_{ref}$ for SEN(T).....	42
14.4.4	$\sigma_{ref}$ for SEN(B) (3 Point Bend Specimen).....	42
14.4.5	$\sigma_{ref}$ for DEN(T).....	42
14.4.6	$\sigma_{ref}$ for M(T).....	43
14.5	$\eta$ Functions for cracked geometries.....	43
14.5.1	Nomenclature (see Figure A.1.3).....	43
14.5.2	Solutions for creep crack growth parameter, C*.....	44
14.5.3	Best fit solutions of $\eta$ from finite element calculations.....	45
14.5.4	Choice of $\eta$ for evaluating C* for material CCI and CCG properties.....	45
14.5.5	Choice of $\eta$ for evaluating C* in life assessment.....	45
14.6	$\eta$ Function Equations.....	46
14.6.1	$\eta$ functions for C(T).....	46
14.6.2	$\eta$ functions for CS(T).....	46
14.6.3	$\eta$ functions for SEN(T).....	46
14.6.4	$\eta$ functions for SEN(B) — 3PB.....	47
14.6.5	$\eta$ functions for DEN(T).....	47
14.6.6	$\eta$ functions for M(T).....	47
14.7	Table for $\eta^{LLD}$ .....	49
14.8	Table for $\eta^{CMOD}$ .....	50
14.9	Geometry Definitions for 'Feature' Type Specimens.....	51
14.9.1	Details form Pipe, Plate and Notched bar 'feature specimens'.....	51
14.10	Fracture Mechanics Functions for Feature Components.....	52
14.10.1	K solutions for pipes and plates.....	52
14.10.2	Reference stress solutions for pipes.....	53
14.10.3	Reference stress solutions for plates.....	53

14.10.4	Stress intensity factor K for the round notch bar .....	54
14.10.5	C* parameter for the notched bar.....	54
15	APPENDIX II :(TDFAD) $K_{mat}^c$ approach for CCI.....	55
15.1	Introduction .....	55
15.2	Nomenclature .....	55
15.3	Failure Assessment Diagram .....	56
15.4	Materials Data Requirements .....	57
16	APPENDIX III: The Q* Parameter .....	61
16.1	Symbols and Designations.....	61
16.2	Scope .....	62
16.3	Specimen Geometry .....	62
16.4	Guideline for Calculation of the Q* parameter.....	62
16.4.1	Crack Growth Analysis .....	62
16.4.2	Crack initiation Analysis .....	63
17	APPENDIX IV: Local CTOD Approach .....	64
17.1	Crack Tip Opening Displacement (CTOD).....	64
18	APPENDIX V: Further Detailed Advice on Testing .....	66
18.1	Advice on Testing and Machine Specification .....	66
18.2	Loading Machine.....	66
18.3	Machine Tolerances .....	66
18.4	Grips.....	66
18.5	Alignment .....	66
18.6	Specimen Dimensional Measurement .....	67
18.7	Specimen Preparation .....	67
18.8	Permissible Temperature Deviation.....	67
18.9	Temperature Hold-time before start of Test.....	67
18.10	Thermocouple Junction and Wiring .....	67
18.11	Thermocouple Attachment .....	68
18.12	Verification of Thermocouple .....	68
18.13	Application of Load .....	68
18.14	Loading Precautions .....	68
18.15	Displacement Measurement .....	68
18.16	Apparatus for Crack Size Measurement.....	69
18.17	Potential Difference (PD) Performance .....	69
18.18	Specimen Preparation for Electric Potential Measurement .....	69
18.19	Premature Test Failure .....	69
18.20	Recommended Method for Treating Extensive Plasticity .....	69
18.21	Recommended Data Reduction Techniques .....	70
18.21.1	Calculating the cracking and displacement rates .....	70
18.21.2	Method for calculating the cracking and displacement rates.....	70
18.21.3	Secant method for deriving CCG and displacement rates .....	70
18.21.4	Incremental polynomial method to derive CCG and displacement rates .....	70
18.21.5	Calculating crack length .....	71
18.21.6	Voltage versus crack length relation .....	71
19	REFERENCES – Related International Standards and Codes .....	72
20	REFERENCES – Relevant Publications.....	74