

ISO/TR 12116:2008-07 (E)

Textiles - Methods of simulating colour change during actual wear by means of laboratory colour-fastness tests

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Principle	1
4	Test specimens	2
4.1	General	2
4.2	Method 1 and method 3	2
4.3	Method 2	2
4.4	Method 4	2
5	Test procedures	2
5.1	Method 1	2
5.2	Method 2	3
5.3	Method 3	4
5.4	Method 4	4
5.5	Assessment	4
5.6	Number of test cycles	5
6	Test report	5
Annex A (informative) Relationship between laboratory testing and actual wear		6
Bibliography		7