

DIN 50969-1:2009-06 (E)

Prevention of hydrogen-induced brittle fracture of high-strength steel building elements - Part 1: Advice on the prevention

Contents		Page
Foreword		3
Introduction		4
1	Scope	5
2	General	5
3	Measures to be taken at the design and manufacturing stages	5
3.1	Design measures	5
3.2	Material-related measures	5
3.3	Manufacture-related measures	6
3.4	Minimizing residual tensile stresses	6
4	Coating process	6
4.1	General	6
4.2	Pretreatment for activation of the surface for subsequent coatings	7
4.3	Coating	7
4.4	Heat treatment after coating	7
Bibliography		8