

ISO 5398-2:2009-01 (E)

Leather — Chemical determination of chromic oxide content —
Part 2: Quantification by colorimetric determination

Contents		Page
Foreword.....		iv
Introduction		v
1 Scope		1
2 Normative references		1
3 Terms and definitions.....		1
4 Principle		1
5 Sampling and sample preparation		2
6 Reagents		2
6.1 Alkaline fusion method		2
6.2 Photometric determination		2
7 Apparatus		2
8 Methods		3
8.1 Alkaline fusion method		3
8.2 Measurement of the aqueous solution.....		3
8.3 Preparation of the calibration solution.....		3
9 Check of the analytical system		4
10 Calculation and expression of results.....		4
10.1 General.....		4
10.2 Repeatability.....		4
11 Test report		5
Annex A (informative) Determination of water and other volatile matter		6