

DIN EN ISO 3613:2011-04 (E)

Metallic and other inorganic coatings - Chromate conversion coatings on zinc, cadmium, aluminium-zinc alloys and zinc-aluminium alloys - Test methods (ISO 3613:2010)

Contents		Page
Foreword		3
Introduction		4
1	Scope	5
2	Normative references	5
3	Reagents	6
4	Apparatus	7
5	Test methods	7
5.1	General	7
5.2	Test for the presence of a colourless chromate coating on zinc	8
5.3	Test for the presence of a colourless chromate coating on zinc and cadmium	8
5.4	Test for the presence of a colourless chromate coating on and zinc-aluminium (mass fraction of aluminium: 5 %) alloys	9
5.5	Test for the presence of hexavalent chromium in both colourless and coloured chromate coatings	9
5.5.1	Test method employing test solution C 1	9
5.5.2	Test method employing alternative test solution C 2 (destructive)	9
5.5.3	Expression of results	10
5.6	Determination of hexavalent chromium content of coloured chromate coatings	10
5.6.1	Preparation of calibration graph	10
5.6.2	Blank test	10
5.6.3	Determination	10
5.6.4	Expression of results	11
5.7	Determination of total chromium content of coloured chromate coatings	11
5.7.1	Preparation of calibration graph	11
5.7.2	Blank test	11
5.7.3	Determination	11
5.7.4	Expression of results	11
5.8	Determination of mass per unit area of both colourless and coloured chromate coatings by gravimetric method	11
5.9	Test for adhesion by abrasion	12
5.10	Quality evaluation test of chromate layers on zinc and cadmium surfaces	12
6	Test report	12
Bibliography		13