

DIN EN 16016-3:2012-01 (E)

Non destructive testing - Radiation methods - Computed tomography - Part 3: Operation and interpretation

Contents		Page
Foreword		3
Introduction		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	5
4	Operational procedure	5
4.1	General	5
4.2	CT system set-up	5
4.2.1	General	5
4.2.2	Geometry	5
4.2.3	X-ray source	6
4.2.4	Detector	6
4.3	Reconstruction parameters	7
4.4	Visualisation	7
4.5	Analysis and interpretation of CT images	7
4.5.1	General	7
4.5.2	Feature testing/defect testing	7
4.5.3	Dimensional testing	8
5	Requirements for acceptable results	10
5.1	Image quality parameters	10
5.1.1	Contrast	10
5.1.2	Noise	12
5.1.3	Signal to noise ratio	12
5.1.4	Contrast to noise ratio	12
5.1.5	Spatial resolution	13
5.2	Suitability of testing	15
5.3	CT examination interpretation and acceptance criteria	15
5.4	Records and reports	15
5.5	Artefacts	16
5.5.1	General	16
5.5.2	Beam hardening artefacts	16
5.5.3	Edge artefacts	17
5.5.4	Scattered radiation	18
5.5.5	Instabilities	18
5.5.6	Ring artefacts	18
5.5.7	Centre of rotation error artefacts	19
5.5.8	Motion artefacts	20
5.5.9	Artefacts due to an insufficient number of projections	21
5.5.10	Cone beam artefacts	21
Annex A (informative)	Spatial resolution measurement using line pair gauges	23
A.1	Line pair gauges	23
A.2	Principle of measurement	24
Bibliography		27