

ISO 12111:2011-08 (E)

Metallic materials - Fatigue testing - Strain-controlled thermomechanical fatigue testing method

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols	3
5	Apparatus	4
5.1	Testing machine	4
5.2	Strain measuring system	5
5.3	Heating system	5
5.4	Instrumentation for test monitoring	5
5.5	Checking and verification of the apparatus	6
6	Specimens	6
6.1	Geometry	6
6.2	Preparation of specimens	9
6.3	Machining procedure	10
6.4	Sampling and marking	10
6.5	Surface condition of the specimen	11
6.6	Dimensional check	11
6.7	Storage and handling of specimens	11
7	Procedure	12
7.1	Laboratory environment	12
7.2	Specimen mounting	12
7.3	Temperature control	12
7.4	Temperature gradients	12
7.5	Mechanical strain control	13
7.6	Thermal strain compensation	13
7.7	Temperature/mechanical strain phasing	15
7.8	Command waveforms	16
7.9	Start of test	16
7.10	Monitoring the test	17
7.11	Failure criteria	17
7.12	Failure	18
7.13	Test interruption sequence	18
8	Expression of results	18
8.1	Preliminary data	18
8.2	Reduction of recorded data	18
8.3	Analysis of results	18
9	Test report	19
9.1	Aim of the study	19
9.2	Material	19

9.3	Specimen	19
9.4	Test equipment details	19
9.5	Description of test methodology	19
9.6	Test termination technique including definition of failure	19
9.7	Deviations from specified test tolerances or recommended procedures	19
9.8	Test conditions	20
9.9	Presentation of results	20
Annex A (informative) Representative diagrams		21
Annex B (informative) Modulus of elasticity determination		24
Bibliography		25