

ISO 7539-6:2011-10 (E)

Corrosion of metals and alloys - Stress corrosion testing - Part 6: P reparation and use of precracked specimens for tests under constant load or constant displacement

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Principle	4
5	Specimens	5
5.1	General	5
5.2	Specimen design	6
5.3	Stress intensity factor considerations	17
5.4	Specimen preparation	22
5.5	Specimen identification	23
6	Initiation and propagation of fatigue cracks	23
7	Procedure	25
7.1	General	25
7.2	Environmental considerations	25
7.3	Environmental chamber	26
7.4	Environmental control and monitoring	27
7.5	Determination of KISCC by crack arrest	28
7.6	Determination of KISCC by crack initiation	31
7.7	Measurement of crack velocity	32
8	Test report	33
Annex A (normative) Use of notched specimens for stress corrosion tests		35
Annex B (normative) Determination of crack growth velocity		38