

ISO 14719:2011-12 (E)

Chemical analysis of refractory material glass and glazes - Determination of Fe<(hoch)2+> and Fe<(hoch)3+> by the spectra I photometric method with 1,10-phenanthroline

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle of Methods A and B	2
5	Sample preparation	2
6	Interferences	2
7	Sample disintegration and measurement	2
8	Calculation and expression of results	9
9	Test report	10
Annex A (informative) Precision		11
Bibliography		13