

# ISO 14802:2012-07 (E)

## Corrosion of metals and alloys - Guidelines for applying statistics to analysis of corrosion data

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
1	Scope .....	1
2	Significance and use .....	1
3	Scatter of data .....	1
3.1	Distributions .....	1
3.2	Histograms .....	1
3.3	Normal distribution .....	2
3.4	Normal probability paper .....	2
3.5	Other probability paper .....	2
3.6	Unknown distribution .....	3
3.7	Extreme value analysis .....	3
3.8	Significant digits .....	3
3.9	Propagation of variance .....	3
3.10	Mistakes .....	3
4	Central measures .....	3
4.1	Average .....	3
4.2	Median .....	4
4.3	Which to use .....	4
5	Variability measures .....	4
5.1	General .....	4
5.2	Variance .....	4
5.3	Standard deviation .....	5
5.4	Coefficient of variation .....	5
5.5	Range .....	5
5.6	Precision .....	6
5.7	Bias .....	6
6	Statistical tests .....	6
6.1	Null hypothesis .....	6
6.2	Degrees of freedom .....	7
6.3	t-Test .....	7
6.4	F-test .....	8
6.5	Correlation coefficient .....	8
6.6	Sign test .....	9
6.7	Outside count .....	9
7	Curve fitting--Method of least squares .....	9
7.1	Minimizing variance .....	9
7.2	Linear regression -- 2 variables .....	9
7.3	Polynomial regression .....	10
7.4	Multiple regression .....	10
8	Analysis of variance .....	11
8.1	Comparison of effects .....	11
8.2	The two-level factorial design .....	11

<b>9</b>	<b>Extreme value statistics</b> .....	<b>11</b>
<b>9.1</b>	<b>Scope of this clause</b> .....	<b>11</b>
<b>9.2</b>	<b>Gumbel distribution and its probability paper</b> .....	<b>12</b>
<b>9.3</b>	<b>Estimation of distribution parameters</b> .....	<b>13</b>
<b>9.4</b>	<b>Report</b> .....	<b>15</b>
<b>9.5</b>	<b>Other topics</b> .....	<b>15</b>
<b>Annex A (informative) Sample calculations</b> .....		<b>46</b>
<b>Bibliography</b> .....		<b>60</b>