

# ISO 105-B02:2014-09 (E)

## Textiles - Tests for colour fastness - Part B02: Colour fastness to artificial light: Xenon arc fading lamp test

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Principle .....</b>	<b>1</b>
<b>4</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>5</b>	<b>Materials and apparatus .....</b>	<b>3</b>
<b>5.1</b>	<b>Reference materials .....</b>	<b>3</b>
<b>5.2</b>	<b>Laboratory exposure devices .....</b>	<b>4</b>
<b>6</b>	<b>Preparation of test specimens .....</b>	<b>5</b>
<b>7</b>	<b>Exposure conditions .....</b>	<b>6</b>
<b>8</b>	<b>Procedure .....</b>	<b>7</b>
<b>8.1</b>	<b>Apparatus set-up .....</b>	<b>7</b>
<b>8.2</b>	<b>Adjustment of the effective humidity (see Clause 7 and Annex E) .....</b>	<b>7</b>
<b>8.3</b>	<b>Exposure methods .....</b>	<b>9</b>
<b>9</b>	<b>Assessment of colour fastness .....</b>	<b>16</b>
<b>10</b>	<b>Test report .....</b>	<b>17</b>
<b>Annex A (normative) Requirements for xenon arc exposure devices .....</b>		<b>20</b>
<b>Annex B (normative) Procedures for measuring the irradiance uniformity in the specimen exposure area (for apparatus manufacturers only) .....</b>		<b>23</b>
<b>Annex C (informative) Light exposure equivalents for blue wool lightfastness references L2 to L9 ..</b>		<b>25</b>
<b>Annex D (informative) General information on colour fastness to light .....</b>		<b>26</b>
<b>Annex E (informative) Guidelines for conducting testing .....</b>		<b>28</b>
<b>Bibliography .....</b>		<b>36</b>