

ISO 19830:2015-11 (E)

Surface chemical analysis - Electron spectroscopies - Minimum reporting requirements for peak fitting in X-ray photoelectron spectroscopy

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Terms and definitions	1
3	Symbols and abbreviated terms	2
3.1	Abbreviated terms	2
3.2	Symbols	2
4	Reporting of relevant data acquisition parameters	3
4.1	General	3
4.2	Spectrometer	3
4.3	Instrument resolution	3
4.4	Detector	3
4.5	X-ray source	4
4.6	Element identity	4
4.7	Energy range in the spectrum	4
4.8	Energy step size in spectrum	4
4.9	Charge compensation	4
5	Reporting of single-spectrum peak-fitting parameters	5
5.1	General	5
5.2	Background range	5
5.3	Background integration range	5
5.4	Background type	5
5.5	Application of a fitted background	5
5.6	Setting the peak parameters	6
5.7	Peak area and peak height	6
5.8	Peak area and peak height ratios	6
5.9	Full width at half maximum	6
5.10	Peak shape	6
5.11	Peak asymmetry parameters	7
5.12	The peak-fitting process	7
5.13	Residual spectrum	7
6	Multi-spectrum peak fitting	7
6.1	General	7
6.2	Peak fitting methods for multi-spectrum data sets	7
6.3	Propagation of constraints	8
6.4	Background propagation	8
7	Satellite subtraction	9
8	Doublet subtraction	9
9	Spectrum deconvolution	10
10	Fit quality and uncertainties	10

10.1	General	10
10.2	Fit quality	10
10.3	Uncertainty in the reported binding energies	10
10.4	Uncertainty in the peak areas	10
Annex A (informative) Example of reporting peak fitting		11
Annex B (informative) Reporting peak fitting for multi-level data sets		14
Annex C (informative) Template for reporting peak fitting parameters		17
Annex D (informative) Statistical methods		19
Bibliography		22