

# ISO 16700:2016-08 (E)

## Microbeam analysis - Scanning electron microscopy - Guidelines for calibrating image magnification

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Image magnification .....</b>	<b>3</b>
<b>4.1</b>	<b>Scale marker .....</b>	<b>3</b>
<b>4.2</b>	<b>Expressing magnification .....</b>	<b>3</b>
<b>5</b>	<b>Reference material .....</b>	<b>3</b>
<b>5.1</b>	<b>General .....</b>	<b>3</b>
<b>5.2</b>	<b>Requirements for CRM .....</b>	<b>4</b>
<b>5.3</b>	<b>Pitch patterns on CRM .....</b>	<b>4</b>
<b>5.4</b>	<b>Storage and handling .....</b>	<b>4</b>
<b>6</b>	<b>Calibration procedures .....</b>	<b>5</b>
<b>6.1</b>	<b>General .....</b>	<b>5</b>
<b>6.2</b>	<b>Mounting CRM .....</b>	<b>5</b>
<b>6.3</b>	<b>Setting SEM operation conditions for calibration .....</b>	<b>5</b>
<b>6.4</b>	<b>Image recording .....</b>	<b>6</b>
<b>6.5</b>	<b>Measurement of image .....</b>	<b>6</b>
<b>6.6</b>	<b>Calibration of magnification and scale marker .....</b>	<b>7</b>
<b>6.6.1</b>	<b>General .....</b>	<b>7</b>
<b>6.6.2</b>	<b>Magnification .....</b>	<b>7</b>
<b>6.6.3</b>	<b>Scale marker .....</b>	<b>7</b>
<b>7</b>	<b>Accuracy of image magnification and scale marker .....</b>	<b>8</b>
<b>8</b>	<b>Calibration report .....</b>	<b>9</b>
<b>8.1</b>	<b>General .....</b>	<b>9</b>
<b>8.2</b>	<b>of calibration report .....</b>	<b>9</b>
<b>Annex A (informative) Reference materials for magnification .....</b>		<b>11</b>
<b>Annex B (informative) Parameters that influence the resultant magnification of an SEM .....</b>		<b>13</b>
<b>Annex C (informative) Uncertainties in magnification measurements .....</b>		<b>15</b>
<b>Annex D (informative) Example of a test report .....</b>		<b>16</b>
<b>Bibliography .....</b>		<b>18</b>