

# ISO 12106:2017-03 (E)

## Metallic materials - Fatigue testing - Axial-strain-controlled method

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
Introduction .....		vi
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Symbols .....	3
4.1	Specimens .....	3
4.2	Fatigue testing .....	3
4.2.1	Symbols .....	3
4.2.2	Subscripts .....	5
4.3	Expression of results .....	5
5	Apparatus .....	5
5.1	Test machine .....	5
5.1.1	General .....	5
5.1.2	Force transducer .....	6
5.1.3	Gripping of specimen .....	6
5.1.4	Alignment check .....	6
5.2	Strain measurement .....	7
5.3	Heating device and temperature measurement .....	8
5.4	Instrumentation for test monitoring .....	8
5.4.1	Recording systems .....	8
5.4.2	Cycle counter .....	9
5.5	Checking and verification .....	9
6	Specimens .....	9
6.1	Geometry .....	9
6.1.1	Round bars .....	9
6.1.2	Flat sheet products .....	10
6.2	Preparation of specimens .....	14
6.2.1	General .....	14
6.2.2	Machining procedure .....	14
6.2.3	Sampling and marking .....	15
6.2.4	Surface condition of specimen .....	15
6.2.5	Dimensional check .....	16
6.2.6	Storage and handling .....	16
7	Procedure .....	16
7.1	Laboratory environment .....	16
7.2	Test machine control .....	16
7.3	Mounting of the specimen .....	17
7.4	Cycle shape -- Strain rate or frequency of cycling .....	17
7.5	Start of test .....	18
7.5.1	Preliminary measurements .....	18
7.5.2	Test commencement .....	19
7.6	Number of specimens .....	19
7.7	Data recording .....	19

7.7.1	Stress-strain hysteresis loops .....	19
7.7.2	Data acquisition .....	19
7.8	End of test .....	20
7.9	Failure criteria .....	20
8	High-temperature strain-controlled creep-fatigue testing .....	22
9	Expression of results .....	23
9.1	Basic data (recorded data (see 7.7)) .....	23
9.2	Analysis of low-cycle fatigue results at $R_e = -1$ .....	23
9.2.1	Distinction between different types of strain values .....	23
9.2.2	Determination of fatigue life (see 7.9) .....	24
9.2.3	Stress-strain and strain-fatigue life relationships .....	24
9.3	Analysis of creep-fatigue results .....	25
10	Test report .....	25
10.1	General .....	25
10.2	Purpose of the test .....	26
10.3	Material .....	26
10.4	Specimen .....	26
10.5	Test methods .....	26
10.6	Test conditions .....	27
10.7	Presentation of results .....	27
10.7.1	Presentation of single test results .....	27
10.7.2	Presentation of results of test series .....	28
10.8	Values to be stored in a low-cycle fatigue database .....	29
	Annex A (informative) Measurement uncertainty .....	31
	Annex B (informative) Examples of graphical presentation of results .....	33
	Bibliography .....	37