

# ISO 14713-3:2017-04 (E)

## Zinc coatings - Guidelines and recommendations for the protection against corrosion of iron and steel in structures - Part 3: Sherardizing

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Design for sherardizing .....</b>	<b>2</b>
4.1	General .....	2
4.2	Surface preparation .....	2
4.3	Design considerations .....	3
4.4	Clearances of threaded components .....	3
<b>5</b>	<b>Storage and transport .....</b>	<b>4</b>
5.1	General .....	4
5.2	Recommendations for storage and transport .....	4
<b>6</b>	<b>Effects of article condition on quality of sherardizing .....</b>	<b>4</b>
6.1	Composition .....	4
6.2	Surface condition .....	4
6.3	Influence of steel surface roughness on the sherardized coating thickness .....	5
6.4	Internal stresses in the base material .....	5
6.4.1	General .....	5
6.4.2	Distortion cracking .....	5
6.4.3	Hydrogen embrittlement .....	6
6.5	Large objects and thick steels .....	6
<b>7</b>	<b>Effect of sherardizing process on the article .....</b>	<b>6</b>
7.1	Processing circumstances .....	6
7.2	Coating properties influenced by the sherardizing process .....	6
7.2.1	Sherardizing practice .....	6
7.2.2	Surface properties of the finished article .....	6
<b>8</b>	<b>After-treatments .....</b>	<b>7</b>
Bibliography .....		8