

# ISO 1099:2017-06 (E)

## Metallic materials - Fatigue testing - Axial force-controlled method

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Test plan .....	3
4.1	General outline .....	3
4.2	Presentation of fatigue results .....	4
4.2.1	General .....	4
4.2.2	Wöhler or S-N curve .....	4
4.2.3	Mean stress diagrams .....	4
5	Shape and size of specimen .....	4
5.1	Form of specimens .....	4
5.2	Specimen temperature measurement .....	5
6	Geometry .....	5
6.1	Bars and flat sheets >5 mm thick .....	5
6.2	Flat sheets .....	6
6.2.1	General .....	6
6.2.2	Thicknesses between 5 mm and 2,5 mm .....	6
6.2.3	Thicknesses <2,5 mm .....	6
6.3	Preparation of specimens .....	6
6.3.1	Machining procedure .....	7
6.3.2	Sampling and marking .....	7
6.3.3	Surface condition of the specimen .....	7
6.3.4	Dimensional checks .....	8
6.3.5	Storage and handling .....	8
7	Apparatus .....	8
7.1	Test machine .....	8
7.2	Alignment check .....	9
7.3	Force transducer .....	9
7.4	Gripping of specimen .....	9
8	Instrumentation for test monitoring .....	10
8.1	Recording systems .....	10
8.2	Cycle counter .....	10
9	Checking and verification .....	10
10	Mounting of specimen .....	10
11	Rate of testing .....	10
12	Application of force .....	11

13	Recording of temperature and humidity .....	11
14	Criterion of failure and test termination .....	11
14.1	Criterion of failure .....	11
14.2	Test termination .....	11
15	Test report .....	11
	Bibliography .....	23