

ISO 4259-1:2017-11 (E)

Petroleum and related products - Precision of measurement methods and results - Part 1: Determination of precision data in relation to methods of test

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Stages in the planning of an interlaboratory study for the determination of the precision of a test method	4
4.1	General	4
4.2	Preparing a draft method of test	5
4.3	Planning a pilot study with at least two laboratories	5
4.4	Planning the ILS	5
4.5	Executing the ILS	6
5	Statistical treatment of ILS results	7
5.1	General recommendation	7
5.2	Pre-screen using GESD technique	7
5.3	Transformation of data and outlier tests	8
5.3.1	General	8
5.3.2	Outlier identification after pre-screening	11
5.3.3	Uniformity of repeatability	11
5.3.4	Uniformity of reproducibility	11
5.4	Rejection of complete data (from all laboratories) for a sample	11
5.5	Estimating missing or rejected values	12
5.5.1	One of the two repeat values missing or rejected	12
5.5.2	Both repeat values missing or rejected	12
5.6	Rejection test for outlying laboratories	12
5.7	Confirmation of selected transformation	13
5.7.1	General	13
5.7.2	Identification of excessively influential sample(s)	13
6	Analysis of variance, calculation and expression of precision estimates	14
6.1	General	14
6.2	Analysis of variance	14
6.2.1	Forming the sums of squares for the laboratories × samples interaction sum of squares	14
6.2.2	Forming the sum of squares for the exact analysis of variance	15
6.2.3	Degrees of freedom	15
6.2.4	Mean squares and analysis of variance	15
6.3	Expectation of mean squares and calculation of precision estimates	15
6.3.1	Expectation of mean squares with no estimated values	15
6.3.2	Expectation of mean squares with estimated values	16
6.3.3	Calculation of precision estimates	17
6.4	Expression of precision estimates of a method of test	18
6.5	Specification of scope for the test method	19
7	R/r ratio	20

Annex A (normative) Determination of number of samples required	21
Annex B (informative) Derivation of formula for estimating the number of laboratories and samples required to meet minimum 30 degrees of freedom	23
Annex C (normative) Notation and tests	25
Annex D (normative) Illustration of procedures using ILS results for Bromine Number and statistical tables	30
Annex E (normative) Types of dependence and corresponding transformations	49
Annex F (normative) Weighted linear regression analysis	55
Annex G (normative) Rules for rounding	62
Annex H (normative) GESD technique to simultaneously identify multiple outliers in a data set	64
Annex I (informative) Glossary	72
Bibliography	75