

# DIN EN ISO 5398-3:2018-10 (E)

## Leather - Chemical determination of chromic oxide content - Part 3: Quantification by atomic absorption spectrometry (ISO 5398-3:2018)

---

<b>Contents</b>	<b>Page</b>
European foreword.....	3
Foreword .....	4
Introduction.....	5
<b>1 Scope</b> .....	<b>6</b>
<b>2 Normative references</b> .....	<b>6</b>
<b>3 Terms and definitions</b> .....	<b>6</b>
<b>4 Principle</b> .....	<b>6</b>
<b>5 Sampling and sample preparation</b> .....	<b>7</b>
<b>6 Reagents</b> .....	<b>7</b>
6.1 Reagents for wet oxidation method.....	7
6.2 Reagents for atomic absorption spectrometry.....	7
<b>7 Apparatus</b> .....	<b>7</b>
<b>8 Methods</b> .....	<b>8</b>
8.1 Preparation of analytical solution.....	8
8.1.1 Wet oxidation method.....	8
8.1.2 Microwave digestion method.....	8
8.2 Measurement of the aqueous solution.....	8
8.2.1 General.....	8
8.2.2 Preparation of calibration graph.....	8
8.2.3 Analysis of the test solution.....	8
<b>9 Calculation and expression of results</b> .....	<b>9</b>
<b>10 Test report</b> .....	<b>9</b>
<b>Annex A (informative) Determination of water and other volatile matter</b> .....	<b>10</b>
<b>Annex B (informative) Suitable atomic absorption spectrometry (AAS) equipment</b> .....	<b>11</b>