

ISO 7539-6:2018 (E)

Corrosion of metals and alloys — Stress corrosion testing — Part 6: Preparation and use of precracked specimens for tests under constant load or constant displacement

Contents

	Foreword
1	Scope
2	Normative references
3	Terms and definitions
4	Principle
5	Specimens
5.1	General
5.2	Specimen design
5.3	Stress intensity factor considerations
5.4	Specimen preparation
5.5	Specimen identification
6	Initiation and propagation of fatigue cracks
7	Procedure
7.1	General
7.2	Environmental considerations
7.3	Environmental chamber
7.4	Environmental control and monitoring
7.5	Determination of KISCC by crack arrest
7.6	Determination of KISCC by crack initiation
7.7	Measurement of crack velocity
8	Test report
Annex A	(informative) Use of notched specimens for stress corrosion tests
A.1	General
A.2	Symbols
A.3	Principle
A.4	Specimens
A.4.1	General
A.4.2	Specimen design
A.4.3	Stress considerations
A.4.4	Specimen preparation
A.5	Procedure
A.6	Test report
Annex B	(informative) Determination of crack growth velocity