

ISO 4666-4:2018 (E)

Rubber, vulcanized — Determination of temperature rise and resistance to fatigue in flexometer testing — Part 4: Constant-stress flexometer

Contents

	Foreword
	Introduction
1	Scope
2	Normative references
3	Terms and definitions
4	Principle
5	Apparatus
5.1	Anvils
5.2	Oscillator
5.3	Displacement detector
5.4	Load detector
5.5	Heating chamber and temperature controller
5.6	Needle-type temperature detector
5.7	Temperature-detector position controller
5.8	Computer control unit
5.9	Measuring gauge
6	Calibration
7	Test piece
8	Test conditions
9	Procedure
9.1	General test procedure
9.2	Determination of fatigue life
9.2.1	Practical method
9.2.2	Automatic method
9.2.2.1	General
9.2.2.2	Parameter for detecting breakdown
9.2.2.3	Determination of the criteria for breakdown
9.2.2.4	Determination of the point at which breakdown can be assumed to have occurred
9.3	Determination of changes in specific parameters
9.3.1	Temperature rise
9.3.2	Creep
9.3.3	Compression set
9.3.4	Dynamic properties
10	Precision
11	Test report
Annex A	(informative) Precision
A.1	General
A.2	Precision details
A.3	Precision results
A.4	Usage of precision results

Annex B (normative) Calibration schedule

- B.1 Inspection**
- B.2 Schedule**

Page count: 20