

ISO 21432:2019-12 (E)

Non-destructive testing - Standard test method for determining residual stresses by neutron diffraction

Contents		Page
Foreword		v
Introduction		vii
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols and abbreviated terms	5
4.1	Symbols and units	5
4.2	Subscripts	7
4.3	Abbreviated terms	7
5	Summary of method	7
5.1	General	7
5.2	Outline of the principle – Bragg's law	7
5.3	Neutron sources	7
5.4	Strain determination	8
5.4.1	General	8
5.4.2	Monochromatic instrument	8
5.4.3	TOF instrument	8
5.5	Neutron diffractometers	9
5.6	Stress determination	9
6	Purpose, geometry and material	14
6.1	General	14
6.2	Purpose of the measurement	14
6.3	Geometry	14
6.4	Composition	14
6.5	Thermal/mechanical history	15
6.6	Phases and crystal structures	15
6.7	Homogeneity	15
6.8	Microstructure	15
6.9	Texture	15
7	Preparations for measurements	15
7.1	General	15
7.2	Alignment and calibration of the instrument	15
7.3	Choice of diffraction conditions	16
7.3.1	Monochromatic instruments	16
7.3.2	TOF instruments	18
7.4	Positioning procedures	19
7.5	Gauge volumes	19
7.6	Methods for establishing the macroscopically stress-free or reference lattice spacing	20
8	Measurement and recording requirements	22
8.1	General	22
8.2	Recording requirements	22
8.2.1	General	22

8.2.2	General information -- instrument	22
8.2.3	General information -- specimen	23
8.2.4	Specific information required for each diffraction measurement	23
8.3	Specimen co-ordinates	24
8.4	Positioning of the specimen	24
8.5	Measurement directions	24
8.6	Number and location of measuring positions	24
8.7	Gauge volume	25
8.8	Gauge volume centroid considerations	25
8.9	Temperature	25
9	Calculation of stress	25
9.1	General	25
9.2	Normal stress determinations	25
9.3	Stress state determinations	26
9.3.1	General	26
9.3.2	The sin ² method	26
9.4	Choice of elastic constants	27
9.5	Diffraction data analysis	27
9.5.1	General	27
9.5.2	Peak fitting function	27
9.5.3	Background function	28
9.5.4	Peak to background ratio	28
9.5.5	Distorted peak profiles	28
10	Reliability	29
11	Reporting	30
11.1	General	30
11.2	Strain or stress values	30
11.2.1	General	30
11.2.2	Stress-free or reference lattice spacing	30
11.2.3	Conversion of strain to stress	30
11.2.4	Elastic constants	30
11.2.5	Positioning	30
11.3	Neutron source and instrument	30
11.4	General measurement procedures	31
11.5	Specimens/materials properties	31
11.6	Original data	31
11.7	Uncertainties and errors	31
Annex A (informative)	Measurement and analysis methodologies	32
Annex B (informative)	Determination of uncertainties in a measurand	41
Bibliography	44