

# DIN EN ISO 21432:2021-05 (E)

## Non-destructive testing - Standard test method for determining residual stresses by neutron diffraction (ISO 21432:2019)

---

<b>Contents</b>	<b>Page</b>
<b>European foreword</b> .....	<b>4</b>
<b>Foreword</b> .....	<b>5</b>
<b>Introduction</b> .....	<b>7</b>
<b>1 Scope</b> .....	<b>8</b>
<b>2 Normative references</b> .....	<b>8</b>
<b>3 Terms and definitions</b> .....	<b>8</b>
<b>4 Symbols and abbreviated terms</b> .....	<b>12</b>
4.1 Symbols and units .....	12
4.2 Subscripts .....	14
4.3 Abbreviated terms .....	14
<b>5 Summary of method</b> .....	<b>14</b>
5.1 General .....	14
5.2 Outline of the principle — Bragg's law .....	14
5.3 Neutron sources .....	14
5.4 Strain determination .....	15
5.4.1 General .....	15
5.4.2 Monochromatic instrument .....	15
5.4.3 TOF instrument .....	15
5.5 Neutron diffractometers .....	16
5.6 Stress determination .....	16
<b>6 Purpose, geometry and material</b> .....	<b>21</b>
6.1 General .....	21
6.2 Purpose of the measurement .....	21
6.3 Geometry .....	21
6.4 Composition .....	21
6.5 Thermal/mechanical history .....	22
6.6 Phases and crystal structures .....	22
6.7 Homogeneity .....	22
6.8 Microstructure .....	22
6.9 Texture .....	22
<b>7 Preparations for measurements</b> .....	<b>22</b>
7.1 General .....	22
7.2 Alignment and calibration of the instrument .....	22
7.3 Choice of diffraction conditions .....	23
7.3.1 Monochromatic instruments .....	23
7.3.2 TOF instruments .....	25
7.4 Positioning procedures .....	26
7.5 Gauge volumes .....	26
7.6 Methods for establishing the macroscopically stress-free or reference lattice spacing .....	27
<b>8 Measurement and recording requirements</b> .....	<b>29</b>
8.1 General .....	29
8.2 Recording requirements .....	29

8.2.1	General.....	29
8.2.2	General information — instrument.....	29
8.2.3	General information — specimen.....	30
8.2.4	Specific information required for each diffraction measurement .....	30
8.3	Specimen co-ordinates.....	31
8.4	Positioning of the specimen.....	31
8.5	Measurement directions.....	31
8.6	Number and location of measuring positions.....	31
8.7	Gauge volume.....	32
8.8	Gauge volume centroid considerations .....	32
8.9	Temperature.....	32
<b>9</b>	<b>Calculation of stress.....</b>	<b>32</b>
9.1	General.....	32
9.2	Normal stress determinations.....	32
9.3	Stress state determinations .....	33
9.3.1	General.....	33
9.3.2	The $\sin^2\psi$ method.....	33
9.4	Choice of elastic constants.....	34
9.5	Diffraction data analysis.....	34
9.5.1	General.....	34
9.5.2	Peak fitting function.....	34
9.5.3	Background function.....	35
9.5.4	Peak to background ratio.....	35
9.5.5	Distorted peak profiles.....	35
<b>10</b>	<b>Reliability.....</b>	<b>36</b>
<b>11</b>	<b>Reporting.....</b>	<b>37</b>
11.1	General.....	37
11.2	Strain or stress values.....	37
11.2.1	General.....	37
11.2.2	Stress-free or reference lattice spacing.....	37
11.2.3	Conversion of strain to stress .....	37
11.2.4	Elastic constants.....	37
11.2.5	Positioning.....	37
11.3	Neutron source and instrument.....	37
11.4	General measurement procedures .....	38
11.5	Specimens/materials properties.....	38
11.6	Original data.....	38
11.7	Uncertainties and errors .....	38
	<b>Annex A (informative) Measurement and analysis methodologies.....</b>	<b>39</b>
	<b>Annex B (informative) Determination of uncertainties in a measurand.....</b>	<b>48</b>
	<b>Bibliography.....</b>	<b>51</b>