

DIN EN ISO 21432:2021-05 (E)

Non-destructive testing - Standard test method for determining residual stresses by neutron diffraction (ISO 21432:2019)

Contents		Page
European foreword		4
Foreword		5
Introduction		7
1	Scope	8
2	Normative references	8
3	Terms and definitions	8
4	Symbols and abbreviated terms	12
4.1	Symbols and units	12
4.2	Subscripts	14
4.3	Abbreviated terms	14
5	Summary of method	14
5.1	General	14
5.2	Outline of the principle — Bragg's law	14
5.3	Neutron sources	14
5.4	Strain determination	15
5.4.1	General	15
5.4.2	Monochromatic instrument	15
5.4.3	TOF instrument	15
5.5	Neutron diffractometers	16
5.6	Stress determination	16
6	Purpose, geometry and material	21
6.1	General	21
6.2	Purpose of the measurement	21
6.3	Geometry	21
6.4	Composition	21
6.5	Thermal/mechanical history	22
6.6	Phases and crystal structures	22
6.7	Homogeneity	22
6.8	Microstructure	22
6.9	Texture	22
7	Preparations for measurements	22
7.1	General	22
7.2	Alignment and calibration of the instrument	22
7.3	Choice of diffraction conditions	23
7.3.1	Monochromatic instruments	23
7.3.2	TOF instruments	25
7.4	Positioning procedures	26
7.5	Gauge volumes	26
7.6	Methods for establishing the macroscopically stress-free or reference lattice spacing	27
8	Measurement and recording requirements	29
8.1	General	29
8.2	Recording requirements	29

8.2.1	General.....	29
8.2.2	General information — instrument.....	29
8.2.3	General information — specimen.....	30
8.2.4	Specific information required for each diffraction measurement	30
8.3	Specimen co-ordinates.....	31
8.4	Positioning of the specimen.....	31
8.5	Measurement directions.....	31
8.6	Number and location of measuring positions.....	31
8.7	Gauge volume.....	32
8.8	Gauge volume centroid considerations	32
8.9	Temperature.....	32
9	Calculation of stress.....	32
9.1	General.....	32
9.2	Normal stress determinations.....	32
9.3	Stress state determinations	33
9.3.1	General.....	33
9.3.2	The $\sin^2\psi$ method.....	33
9.4	Choice of elastic constants.....	34
9.5	Diffraction data analysis.....	34
9.5.1	General.....	34
9.5.2	Peak fitting function.....	34
9.5.3	Background function.....	35
9.5.4	Peak to background ratio.....	35
9.5.5	Distorted peak profiles.....	35
10	Reliability.....	36
11	Reporting.....	37
11.1	General.....	37
11.2	Strain or stress values.....	37
11.2.1	General.....	37
11.2.2	Stress-free or reference lattice spacing.....	37
11.2.3	Conversion of strain to stress	37
11.2.4	Elastic constants.....	37
11.2.5	Positioning.....	37
11.3	Neutron source and instrument.....	37
11.4	General measurement procedures	38
11.5	Specimens/materials properties.....	38
11.6	Original data.....	38
11.7	Uncertainties and errors	38
	Annex A (informative) Measurement and analysis methodologies.....	39
	Annex B (informative) Determination of uncertainties in a measurand.....	48
	Bibliography.....	51