

# DIN EN ISO 8299:2021-04 (E)

**Nuclear fuel technology - Determination of the isotopic and elemental uranium and plutonium concentrations of nuclear materials in nitric acid solutions by thermal-ionization mass spectrometry (ISO 8299:2019); English version EN ISO 8299:2021**

## Contents

	Page
<b>Foreword</b>	<b>v</b>
<b>1 Scope</b>	<b>1</b>
<b>2 Normative references</b>	<b>1</b>
<b>3 Terms and definitions</b>	<b>1</b>
<b>4 Principle</b>	<b>1</b>
<b>5 Reference materials and reagents</b>	<b>2</b>
5.1 Spikes and reference materials	2
5.2 Other chemical reagents	3
5.3 Resin, applicable for separation/purification of Pu and U	4
5.3.1 General	4
5.3.2 Preparation of resin	4
<b>6 Apparatus</b>	<b>5</b>
<b>7 Apparatus for mass spectrometry</b>	<b>6</b>
<b>8 Sample preparation</b>	<b>6</b>
8.1 Subsampling and spiking	6
8.1.1 Pellet or powder samples	7
8.1.2 Concentrated nuclear fuel solution samples (such as reprocessing solution)	7
8.1.3 Plutonium nitrate solution samples (such as product solution from a reprocessing plant)	7
8.1.4 Dried nitrate samples	8
8.2 Chemical valency adjustment	8
8.2.1 Valence adjustment with ferrous solution	8
8.2.2 Valence adjustment with hydrogen peroxide	8
8.3 Sample separation/purification	9
8.3.1 Ion exchange with anion-exchange resin	9
8.3.2 Purification with extraction separation resins (see 5.3.1.2)	10
8.4 Replicate treatments	10
<b>9 Filaments preparation</b>	<b>10</b>
9.1 Degassing of filaments	10
9.2 Sample loading	10
9.2.1 Normal sample loading	10
9.2.2 Graphite loading technique	10
9.2.3 Resin-bead loading on single filaments for Pu samples	11
9.3 Filament mounting (filament assemblies preparation)	11
<b>10 Instrument calibration</b>	<b>11</b>
10.1 Mass calibration	11
10.2 Gain calibration for Faraday multi-detectors	11
10.3 Faraday detector calibration	11
10.4 Mass discrimination calibration	12
<b>11 Isotopic mass spectrometric measurements</b>	<b>12</b>
11.1 Total evaporation measurements using a single or double filament assembly and a multi-Faraday collector system	12
11.2 Bias correction method using a double filament assembly and a multi-Faraday collector system	13

<b>12</b>	<b>Calculation of the results .....</b>	<b>13</b>
12.1	Calculation of ion current intensities .....	13
12.2	Calculation of mean, weighted mean and standard deviation on a set of ratios $x_i$ , ( $i = 1 \dots N$ ) .....	14
12.3	Mass discrimination correction.....	14
12.4	Calculation of the atomic percent abundance $A_i$ .....	14
12.5	Calculation of the isotopic mass percent $W_j$ .....	15
12.6	Calculation of concentration .....	15
12.7	Isotope decay correction.....	16
<b>13</b>	<b>Blanks .....</b>	<b>16</b>
<b>14</b>	<b>Quality control.....</b>	<b>16</b>
<b>15</b>	<b>Measurement uncertainty.....</b>	<b>17</b>
15.1	Elemental assay.....	17
15.2	Isotopic analysis.....	17
<b>16</b>	<b>Interferences .....</b>	<b>18</b>
<b>Annex A (normative) Preparation and standardization of spike solutions.....</b>		<b>19</b>
<b>Bibliography .....</b>		<b>25</b>