

ISO 3892:2000-06 (E)

Conversion coatings on metallic materials - Determination of coating mass per unit area - Gravimetric methods

Contents		Page
Foreword		iv
1	Scope	1
2	Apparatus	1
3	Test pieces	2
4	Reagents and procedures	2
4.1	General	2
4.2	Phosphate coatings on iron and steel	2
4.3	Phosphate coatings on zinc and cadmium	3
4.4	Crystalline phosphate coatings on aluminium and its alloys	3
4.5	Chromate coatings on zinc and cadmium	4
4.6	Chromate and amorphous phosphate coatings on aluminium and its alloys	4
5	Expression of results	5
5.1	Calculation	5
5.2	Measurement uncertainty	5