

ISO 3892:2000-06 (E)

Conversion coatings on metallic materials - Determination of coating mass per unit area - Gravimetric methods

Contents		Page
Foreword		iv
1 Scope		1
2 Apparatus		1
3 Test pieces		2
4 Reagents and procedures		2
4.1 General		2
4.2 Phosphate coatings on iron and steel		2
4.3 Phosphate coatings on zinc and cadmium		3
4.4 Crystalline phosphate coatings on aluminium and its alloys		3
4.5 Chromate coatings on zinc and cadmium		4
4.6 Chromate and amorphous phosphate coatings on aluminium and its alloys		4
5 Expression of results		5
5.1 Calculation		5
5.2 Measurement uncertainty		5