

ISO/TS 23151:2021-09 (E)

Nanotechnologies - Particle size distribution for cellulose nanocrystals

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Abbreviated terms	2
5	Dispersion of CNCs	2
5.1	General considerations	2
5.2	Dispersion of CNCs by sonication	3
5.3	Dynamic light scattering assessment of dispersions	4
5.4	Determination of optimal sonication energy	5
6	Sample preparation for microscopy	5
6.1	General considerations	5
6.2	AFM sample preparation	6
6.3	TEM sample preparation	6
7	Atomic force microscopy	6
7.1	General	6
7.2	Instrumentation and accessories	7
7.3	Microscope calibration	7
7.4	Data acquisition	7
7.5	Image analysis	8
8	Transmission electron microscopy	8
8.1	General	8
8.2	Instrumentation and accessories	9
8.3	Microscope calibration	9
8.4	Data acquisition	9
8.5	Image analysis	9
9	Data analysis	10
9.1	General	10
9.2	Assessment of data quality	10
9.3	Fitting distribution models to data	10
9.4	Measurement uncertainty	11
10	Test report	12
10.1	Atomic force microscopy	12
10.1.1	General information	12
10.1.2	Sample	12
10.1.3	Data acquisition	12
10.1.4	Image analysis	13
10.2	Transmission electron microscopy	13
10.2.1	General information	13
10.2.2	Sample	13

10.2.3	Data acquisition	13
10.2.4	Image analysis	14
Annex A (informative)	Assessment of CNC dispersions	15
Annex B (informative)	Assessment of applied imaging force	16
Annex C (informative)	Interlaboratory comparison results: AFM	18
Annex D (informative)	Interlaboratory comparison results: TEM	25
Bibliography		34