

# ISO 10675-1:2021-12 (E)

## Non-destructive testing of welds - Acceptance levels for radiographic testing - Part 1: Steel, nickel, titanium and their alloys

---

<b>Contents</b>	<b>Page</b>
<b>Foreword</b> .....	<b>iv</b>
<b>1 Scope</b> .....	<b>1</b>
<b>2 Normative references</b> .....	<b>1</b>
<b>3 Terms and definitions</b> .....	<b>1</b>
<b>4 Symbols and abbreviations</b> .....	<b>1</b>
<b>5 Radiographic technique</b> .....	<b>2</b>
<b>6 General</b> .....	<b>2</b>
<b>7 Acceptance levels</b> .....	<b>3</b>
<b>Annex A (informative) Guidance to the limitations of radiographic testing</b> .....	<b>6</b>
<b>Annex B (informative) Examples for determination of area percentage (%) of imperfections</b> .....	<b>7</b>
<b>Annex C (informative) Calculation of the sum of acceptable areas</b> .....	<b>9</b>
<b>Bibliography</b> .....	<b>14</b>