

# ISO 1352:2021-12 (E)

## Metallic materials - Torque-controlled fatigue testing

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b>		<b>v</b>
<b>1</b>	<b>Scope</b>	<b>1</b>
<b>2</b>	<b>Normative references</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions</b>	<b>1</b>
<b>4</b>	<b>Symbols and abbreviated terms</b>	<b>3</b>
<b>5</b>	<b>Principle of test</b>	<b>4</b>
<b>6</b>	<b>Test plan</b>	<b>5</b>
<b>7</b>	<b>Shape and size of specimen</b>	<b>5</b>
7.1	Form	5
7.2	Dimensions	7
7.2.1	Specimens of circular cross-section	7
7.2.2	Specimens with tubular cross-section	8
<b>8</b>	<b>Preparation of specimens</b>	<b>8</b>
8.1	General	8
8.2	Machining procedure	8
8.3	Sampling and marking	9
8.4	Surface conditions of specimen	9
8.5	Dimensional checks	10
8.6	Storage and handling	10
<b>9</b>	<b>Apparatus</b>	<b>10</b>
9.1	Testing machine	10
9.1.1	General	10
9.1.2	Torque cell	10
9.1.3	Gripping of specimen	11
9.1.4	Alignment check	11
9.1.5	Axial force	11
9.2	Heating system	12
9.3	Instrumentation for test monitoring	12
9.3.1	Recording system	12
9.3.2	Cycle counter	12
9.3.3	Checking and verification	13
<b>10</b>	<b>Test procedure</b>	<b>13</b>
10.1	Mounting of specimen	13
10.2	Frequency of testing	13
10.3	Heating for the isothermal elevated temperature test	13
10.4	Application of torque	13
10.5	Calculation of nominal torsional (shear) stress	13
10.6	Recording of temperature and humidity	14
10.7	Failure and termination criteria	14
10.7.1	Failure	14
10.7.2	Termination	14
<b>11</b>	<b>Measurement uncertainty</b>	<b>14</b>
<b>12</b>	<b>Test report</b>	<b>15</b>
<b>Annex A</b> (informative)	<b>Presentation of results</b>	<b>16</b>

<b>Annex B (informative) Verification of alignment of torsional fatigue testing machines</b> .....	<b>20</b>
<b>Annex C (informative) Measuring uniformity of torsional strain (stress) state</b> .....	<b>22</b>
<b>Annex D (informative) Estimation of measurement uncertainty</b> .....	<b>25</b>
<b>Bibliography</b> .....	<b>27</b>