

ISO 9271:2023-02 (E)

Decontamination of radioactively contaminated surfaces - Testing of decontamination agents for textiles

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms, definitions and symbols	1
3.1	Terms and definitions	2
3.2	Symbols	3
4	Principle	3
5	Apparatus	4
5.1	Beakers	4
5.2	Radiation detector	4
5.3	Pipettes	5
5.4	Two polytetrafluoroethylene (PTFE) or quartz ampoules	5
5.5	Thermostat	5
5.6	Storage bottles	5
5.7	Drying cabinet	5
5.8	Mounting	5
5.9	Cage-stirrer apparatus	6
6	Contamination and decontamination agents	6
6.1	Contaminant solutions	6
6.1.1	Composition of contaminant solutions	6
6.1.2	Preparation of the contaminant solutions	6
6.1.3	Storage of the contaminant solution	7
6.2	Decontamination agents	7
7	Contaminated textile specimen	7
7.1	Reference materials	7
7.2	Number and dimensions of contaminated textile specimens	8
8	Procedure	8
8.1	Determining the specific pulse rate of each contaminant solution	8
8.2	Preparation of the textile specimens	8
8.3	Contamination	9
8.3.1	Preparation	9
8.3.2	Procedure	9
8.4	Decontamination	10
8.4.1	Preparation	10
8.4.2	Procedure	10
8.5	Determining the residual pulse rate, I_r	11
9	Calculation of results and assessment of ease of decontamination	11
10	Test report	12

Annex A (informative) Clamp specimen holder	13
Annex B (normative) Cage-stirrer apparatus for decontamination	14
Annex C (informative) Formulae for the preparation of ⁶⁰Co and ¹³⁷Cs or ¹³⁴Cs contaminant solutions	23
Annex D (informative) Example of a test report	26
Bibliography	28