

# ISO 18118:2024-02 (E)

## Surface chemical analysis - Auger electron spectroscopy and X-ray photoelectron spectroscopy - Guide to the use of experimentally determined relative sensitivity factors for the quantitative analysis of homogeneous materials

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Symbols and abbreviated terms .....	4
5	General information .....	5
6	Measurement conditions .....	6
6.1	General .....	6
6.2	Excitation source .....	7
6.3	Energy resolution .....	7
6.4	Energy step and scan rate .....	7
6.5	Signal intensity .....	7
6.6	Gain and time constant (for AES instruments with analogue detection systems) .....	7
6.7	Modulation to generate a derivative spectrum .....	7
7	Data-analysis procedures .....	7
8	Spectrometer response function .....	8
9	Determination of chemical composition using relative sensitivity factors .....	8
9.1	Calculation of chemical composition .....	8
9.1.1	General .....	8
9.1.2	Composition determined from elemental relative sensitivity factors .....	9
9.1.3	Composition determined from atomic relative sensitivity factors or average matrix relative sensitivity factors .....	9
9.2	Uncertainties in calculated compositions .....	9
Annex A (informative) Formulae for relative sensitivity factors .....		10
Annex B (informative) Information on uncertainty of the analytical results .....		16
Bibliography .....		19