

# ISO 105-B04:2024-03 (E)

## Textiles - Tests for colour fastness - Part B04: Colour fastness to artificial weathering: Xenon arc fading lamp test

---

### Contents

Page

- Foreword.....iv
- Introduction.....v
- 1 Scope.....1
- 2 Normative references.....1
- 3 Terms and definitions.....1
- 4 Principle.....2
- 5 Materials.....2
  - 5.1 Blue wool references.....2
  - 5.2 Glass case for blue wool references.....2
  - 5.3 Specimen mounting cards.....2
  - 5.4 Specimen covers.....2
  - 5.5 Specimen holders.....2
  - 5.6 Grey scale for assessing change in colour.....2
- 6 Apparatus.....3
  - 6.1 Laboratory light source.....3
    - 6.1.1 General.....3
    - 6.1.2 Spectral irradiance.....3
  - 6.2 Test chamber.....4
  - 6.3 Radiometer.....5
  - 6.4 Temperature sensors.....5
    - 6.4.1 General.....5
    - 6.4.2 Chamber air temperature thermometer.....5
    - 6.4.3 Black-standard thermometer (BST) and black-panel thermometer (BPT).....5
- 7 Exposure conditions.....5
  - 7.1 General.....5
  - 7.2 Exposure of test specimens.....5
  - 7.3 Exposure of colour fastness references.....6
- 8 Test specimens.....6
- 9 Procedure.....6
  - 9.1 General.....6
  - 9.2 Exposure methods.....7
    - 9.2.1 General.....7
    - 9.2.2 Method 1.....7
    - 9.2.3 Method 2.....7
    - 9.2.4 Method 3.....8
  - 9.3 Drying.....8
  - 9.4 Mounting for assessment.....8
- 10 Assessment of colour fastness to weathering.....8
- 11 Test report.....9
- Annex A (informative) General information on colour fastness to light.....10
- Annex B (informative) Radiometer for controlling exposure duration.....12
- Bibliography.....13